

placing a decor part into an at least two-part injection mold;

closing the mold, thereby cutting the decor part to precise contours in the injection mold by shearing off an outer portion of the decor part;

pressing the cut decor part by injecting a molding compound against a surface of the decor part opposite at least one injection opening;

connecting the injection molding compound with the decor part during hardening of the molding compound, wherein the molding compound forms the carrier; and

opening the injection mold and removing the covering or trim part and molded-on carrier.